

HASTINGS DISTRICT COUNCIL WAS HAPPILY SUPPLYING WATER TO HAVELOCK NORTH.




BORF

HASTINGS DC HAD AN APPROVED WATER SAFETY PLAN, AND A TYPICAL COMPLIANCE HISTORY.

PREVIOUS INVESTIGATIONS SHOWED THE AQUIFER HAD AN INTACT AQUITARD, THE WATER AGE WAS OLD, AND SURROUNDING LANDUSE HAD MINIMAL IMPACT.


BUT IN REALITY...



THE AQUITARD WAS DAMAGED, THERE WERE MANY OLD DISUSED BORES, PONDING OF RUNOFF FROM SHEEP PADDOCKS, AND THE AQUIFER WAS NOT HOMOGENEOUS.

2016 THE NORT 1 2 1 2 8 9 1 6 3 1 6 3 1 6 3 3 1 6 3 3 4 3 1 6 3 3 4 3 1 6 3 3 4 3 1 6 3 3 4 3 1 6 3 3 4 3 4 3 4 3 4 3 4 3 4 3 4 3 4 3 4	3 4 5 6 10 11 12 13 17 18 19 20 24 25 26 27 31	2016 <u>2016</u> <u>3unday</u> 1 7 8 14 15 21 22 28 29	RESUL BAC E	MPLING TS CAME K CLEAR. VERYONE THOUGHT IT WAS FINE.			
WATER LABORATORY DISTRICT HEALTH	VVASN'T RIGHT.						
	Sunday Monday Tuesday 2 9 9 6	Wednesday Thursday 3 4 10 111 17 18	Friday Saturday 5 6 12 1 19 20				
	3	24 25 31	26 27				

AT THE LAB





THE DISTRICT HEALTH BOARD NOTICED LOTS OF GASTRO CASES SO TOLD THE MINISTRY OF HEALTH. THEN AT 2PM, THE DHB HELD AN EMERGENCY MEETING.



STAFF ORDERED ENUMERATED SAMPLING OF THE BORES AND RETICULATION IMMEDIATELY, AND INFORMED THE DHB.



🛑 Hospital 🛑



EMERGENCY CHLORINATION STARTED, AND THE ENTIRE HAVELOCK NORTH RETICULATION SYSTEM VVAS FLUSHED BY MIDNIGHT.

AUGUS

4

17

30

11

24

18

31

3


16

29

10

23

A BOIL WATER NOTICE WAS RELEASED TO MEDIA AND SOCIAL MEDIA



THE NEXT DAY....

6

19

12

25

13

26

20

21

THE DHB ACTIVATED THE EMERGENCY OPERATION CENTRE

AND....


ENUMERATED RESULTS FROM YESTERDAY'S SAMPLES VVERE HIGH... ESTABLISHING THE LINK BETVVEEN THE ILLNESS OUTBREAK AND THE DRINKING VVATER

THE NEXT WEEK

Campylobacter Was identified as the Pathogen.

2016 AUGUS			GU	S	THERE WAS A BIG REDUCTION IN GASTROENTERITIS CASES, AND BY		
Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Sat	25 AUGUST NO NEVV CASES WERE
	1	2	3	4	5		REPORTED.
	8	9	10	11	12	13	Hospital 🔶
		16	17	18	19	20	
			Ļ	25	26	27	
			I				

THE OFFENDING BORES VVERE DEACTIVATED, AND HAVELOCK NORTH VVAS SUPPLIED SOLELY FROM THE HASTINGS SUPPLY, VVHICH VVAS UNDER EMERGENCY CHLORINATION.



AND IN THE FOLLOWING MONTHS




ONE BORE WAS REACTIVATED WITH FILTRATION, UV TREATMENT AND CHLORINATION .


CI


THE BOIL WATER NOTICE WAS LIFTED.

THE INCIDENT IS ESTIMATED TO HAVE CAUSED...



HASTINGS DC CONTINUES TO INSTALL PERMANENT CHLORINATION AND UV TREATMENT ACROSS ALL ITS SYSTEMS.





MAKE SURE IT'S NOT YOUR SYSTEM

